

CLEANING GUIDE FOR

HCL® Medication Cup Dispensers (#7839 & 9401)

Materials:

Acrylic body with Polyethylene cap; Polyurethane mounting tape; Methylene Chloride used to solvent weld acrylic

Recommended Disinfectant Options:

20355 Oxivir® TB Surface Cleaner & Disinfectant Trigger Spray, 32 oz.

19954 PREempt™ One-Step Surface Cleaner and Disinfectant Wipes, 6 x 7, Canister

19955 PREempt™ One-Step Surface Cleaner and Disinfectant, Trigger Spray, 32 oz.

Alternate Disinfectant Options:

None

Follow the cleaner's instructions and adhere to the specific Standard Operating Procedure (SOP) established by your healthcare system.